



Prattville Fire Department

102 West Main Street, Prattville, Alabama 36067

Stanley Gann
Fire Chief

Phone: (334) 361-3660
Fax: (334) 361-3667
Email: prattfire@prattville.com

TO: All HVAC Contractors

FROM: Gene McDaniel

DATE: August 10, 2009

It has been brought to our attention by several of the roofing contractors that we have a problem with the refrigeration lines being hit by their nails, mainly at the bend close to the roof decking. I know that you will be keeping the lines down from the roof, but as time goes by, the lines may get bumped or moved around in order to get up against the decking.

Therefore, in an attempt to avoid this problem, the inspectors are asking that you place a $\frac{3}{4}$ " or greater, board in-between the decking and your refrigeration lines. This will assure adequate spacing in the future.

Thank you for your cooperation.

Gene McDaniel
Building Inspector